

Des. No. A **100**

AIRCRAFT RECORD

Des. No. A-->

Contract No.

Req. **CR-9**

S. E.

Bu-**17**

Cost Price
Flat Price

Contractor **Curtiss Aeroplane Co.**

Address **Buffalo, N.Y.**

Model Type **N-9 Hydro-Tractor School**

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

11/26/16 Pensacola
9/22/17 " wrecked

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

10/12/17

TROUBLE REPORTS

4-4198

Date

Station

Remarks

2

Stricken from list. Dept. letter Oct. 12/17. IO-Z-32.

Des. No. A- 101

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req CR-9

S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type N-9 Hydro-Tractor School

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped

Destination

Received

11/26/16 Pensacola
4/3 & 1/18 Miami
4/30 See A.R. - C.K.

8/1/18

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time **81** Hours **5** Minutes

Stricken from Navy List

11/26/18

2 A-101

TROUBLE REPORTS

4-4198

Date	Station	Remarks
Oct. 31	U.S. Naval Air Station, Miami, Fla.	Body, Lower right and left engine panels, upper engine panel and motor damaged beyond repair. Nose dive at 100 ft. Pilot slightly injured. To be stricken from the Naval Aircraft list. Pilot injured.

Des. No. A- 102

AIRCRAFT RECORD

Des. No. A-1

Contract No.

Req. C.R-9

S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type N-9 Hydro-Tractor School

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air	Date	Wire	S. Order	Shipped	Destination	Received
				11/26/16	Pensacola	
				2/17/17		

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time	Hours	Minutes	Stricken from Navy List
			4/27/17

Des. No. A-103

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-9

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type N-9 Hydro-Tractor School

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

11/24/16 Pensacola
8/17/17 " wrecked

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time Hours Minutes Stricken from Navy List *2/7/18*

Des. No. A- 104

AIRCRAFT RECORD

Des. No. A- -

Contract No.

Req. Cr-9

S. E.

Bu- 17

Cost Price
Flat Price

Contractor

Curtiss Aeroplane Co.

Address

Buffalo, N.Y.

Model

Type N-9 Hydro-Tractor School

Motor

H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Accepted

Op. Air

Date

Wire

S. Order

Shipped

Destination

Received

11/26/16 Pensacola
6/30/18 See Q.R. unfit.

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

7/25/18

TROUBLE REPORTS

4-4193

Date

Station

Remarks

2 A-104
 June 19/18 Pensacola Fla. Machine @ total wreck few parts & fittings salvaged. Machine crashed in mid air with machine A-125 while making @ right turn near Life Saving Sta. block.
 Pilot was instantly killed. Seaplane stricken from the list of Naval Aircraft. All serviceable parts, fittings, etc. be retained at this Sta. Pilot killed.

Des. No. A- 105

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. **CR-9**

S. E.

Bu-17

Cost Price
Flat Price

Contractor **Curtiss Aeroplane Co.**

Address **Buffalo, N.Y.**

Model Type **N-9 Hydro-Tractor School**

Motor H. P. *Converted to land machine* Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

*7/12/17 Pensacola
Sperry Gyro. Co. (Caspique L. I.)
Oakhaven*

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time Hours Minutes Stricken from Navy List *12/19/19*

2 A-105

TROUBLE REPORTS

4-4198

Date

Station

Remarks

5/29/19

Dahlgren

Both plane and engine wrecked beyond repair.
Recommend that this plane be stricken from the Navy
list.

Des. No. A- 106

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-9

S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type N-9 Hydro Tractor School

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

Pensacola

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time Hours Minutes Stricken from Navy List 6/23/17

Des. No. A- 107

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-9

S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type N-9 Hydro-Tractor School

Motor H.P. *Quantity to land machine* Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

assigned to
11/24/16 Pensacola
Sperry Gyro. Co. Copiaque L. I.
Wahlgren

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

12/19/19

TROUBLE REPORTS

4-4198

Date	Station	Remarks
2 8/25/19	A-107 Dahlgren	This plane received from Experimental Station, B. of O., Copaigne, L.I., in a damaged condition. Both plane and engine beyond repair. Recommend it be stricken from the Navy list.

Des. No. A- **108**

AIRCRAFT RECORD

Des. No. A-1

Contract No.

Req. **CR-9**

S. E.

Bu-**17**

Cost Price
Flat Price

Contractor **Curtiss Aeroplane Co.**

Address **Buffalo, N.Y.**

Model **Type N-9 Hydro-Tractor School**

Motor **H. P.**

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% **F. O. B.**

Accepted

Op. Air Date Wire S. Order Shipped

Destination

Received

11/26/16 Pensacola

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

5/9/17

Des. No. A-109

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-9

S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type N-9 Hydro Tractor School

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air	Date	Wire	S. Order	Shipped	Destination	Received
				11/26/16	Pensacola	
				9-1-16	Miami	
				1-7/18	See Q.R.	
				4/5/18	" rebuilding.	

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

6/23/19

2A-109

TROUBLE REPORTS

4-4193

Date	Station	Remarks
4/16/19	Miami	Plane unfit for further use, worn out from long service. Recommended stricken .

Des. No. A-110

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-9

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type N-9 Hydro-Tractor School

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped

Destination

Received

11/24/16 Pensacola

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

6/23/17

Des. No. A- 111

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-9

S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type N-9 Hydro-Tractor School

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

11/26/19
On U.S.S. Seattle
To Sperry Gyro. Co. Capiague L.I.
Sabljren

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

12/19/19

TROUBLE REPORTS

4-4198

Date

Station

Remarks

2 A-111
6/13/19

Dahlgren

Plane and engine wrecked beyond repair. Wings and fuselage caught fire after crash. Recommend that this plane be stricken from the Navy list.

Des. No. A-112

AIRCRAFT RECORD

Des. No. A--

Contract No.

Req. CR-9

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type N-9 Hydro-Tractor School

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped

Destination

Received

11/26/16 U.S.S. Seattle

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

2/16/17

Des. No. A-113

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-9.

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type N-9 Hydro-Tractor School

Motor H. P. *100* Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

Shipped to
U.S. Seattle
Before Aug 17 - Sperry Gyro. Co. Capuaque D.C.
Sahlgren

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

5-18-21

Des. No. A-114

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-9

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type N-9 Hydro-Tractor School

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Accepted

Op. Air	Date	Wire	S. Order	Shipped	Destination	Received
---------	------	------	----------	---------	-------------	----------

11/26/16 U.S.S. Seattle
 2/16/17 Wrecked & surveyed

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List 2/26/17

Des. No. A-115

AIRCRAFT RECORD

Des. No. A---

Contract No.

Req. CR-9

S. E.

- Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type N-9 Hydro-Tractor School

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

11/26/16 Pensacola

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time Hours Minutes Stricken from Navy List *5/19/17*

Des. No. A-116

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-9

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type N-9 Hydro-Tractor School

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Accepted

Op. Air	Date	Wire	S. Order	Shipped	Destination	Received
				11/24/16	U. S. S. Seattle	
				2/16/17	Worked & surveyed	

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

2/26/17

Des. No. A-117

AIRCRAFT RECORD

Des. No. A-117

Contract No.

Req. CR-9

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type N-9 Hydro-Tractor School

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

11/26/16 Pensacola
7/15/17 "
7/12/17 Sperry Gyro Co.

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

8/29/17

Des. No. A- 118

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-9

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type N-9 Hydro-Tractor School

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F.O.B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

assigned to
11/26/16 Pensacola
7/12/17 Sperry Gyro. Co. (at Topique D. I.)

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

4-11-19

*Totally Destroyed
Oct. 21, 1918*

4103

Des. No. A- 119

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-9

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type N-9 Hydro-Tractor School

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

12/4/16 Pensacola
8/2/18 Miami
4/5/18 Rebuilding
4/7/18 See A.P.

*6/22 seen Q. P. ...
rest advised.*

8/1/18

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time 446 Hours

30 Minutes

Stricken from Navy List

4-11-19

4-4198

TROUBLE REPORTS

4-4198

Date 2 Station

1/21/19 Miami, Fla.

Pontoon damaged beyond repair, lower right outer wing section and right aileron damaged beyond repair. Left engine panel damaged beyond repair. Caused by sideslip from 200 ft. altitude. Pilot failed to regain control.

1/17/19 Miami, Fla

Rusty fittings and wires, fabrics torn, needs all new wires, general weak condition. Side slipped from 200 feet. Recommended sticken.

Des. No. A- 120

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-9

S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type N-9 Hydro-Tractor School

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

12/4/16 Pensacola

~~2/10/17~~

2/10/17

1/2/18

10/10/17 Pensacola.

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time Hours Minutes Stricken from Navy List 2/26/18

Des. No. A-121

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-9

S. E.

Bu-17

Cost Price
Flat Price

Contractor

Curtiss Aeroplane Co.

Address

Buffalo, N.Y.

Model

Type N-9 Hydro-Tractor School

Motor

H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air

Date

Wire

S. Order

Shipped

Destination

Received

12/1/16 Pensacola
3/4/18 Miami
4/5/ Rebuilding - Sec. A.R.

2/1/18

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

50

Hours

05

Minutes

Stricken from Navy List

1/9/19.

←4198

TROUBLE REPORTS

4-4198

Date	Station	Remarks
8/23/17	Pensacola,	The left upper longeron of seaplane A-121 in make of the motor burned through while in flight. It is understood that a loosely fitting exhaust manifold connection to the after cylinder together with insufficient lagging over the longeron was the cause of this trouble. Recommended to renew burned portion of longeron by splicing and lag same with abbestoe and copper sheeting.
12/4/18	Miami, Fla.	Crankcase, sump and camshaft broken. #3 piston, cylinder connecting rod and piston pin broken. Piston pin too hard. Caused pin to break and freeze piston in top of cylinder allowing connecting rod to swing free around the crankshaft. Recommended that plane ^{plane} be stricken from the Naval List.
12/11/18	" "	<i>Body, Upper & Lower right wings, Lower left wing, all engine section panels damaged beyond repair due to side slip at 100ft alt. Motor 1425. Lack of judgement. Recommend plane be stricken from list.</i>

2 A-121

Des. No. A-122

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-9

S. E.

Bu-17

Cost Price
Flat Price

Contractor

Curtiss Aeroplane Co.

Address

Buffalo, N.Y.

Model

Type N-9 Hydro-Tractor School

Motor

H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Accepted

Op. Air

Date

Wire

S. Order

Shipped

Destination

Received

2/10/17

Pensacola

2/10/17

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

8/23/17

TROUBLE REPORTS

Date

Station

Remarks

4-4198

2 A-122
9/10/19 Chatham

Unfit for observation or for test hops as the bag is porous all over; the suspensions are weak; the basket needs thorough overhauling. Has been constantly used for nearly a year. Recommend it be stricken from the Navy list and left on station, to be used in instructing recruits in fabric work, patching, etc.

Des. No. A- 123

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-9

S. E.

Bu- 17

Cost Price
Flat Price

Contractor

Curtiss Aeroplane Co.

Address

Buffalo, N.Y.

Model

Type N-9 Hydro-Tractor School

Motor

H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Accepted

Op. Air

Date

Wire

S. Order

Shipped

Destination

* Received

12/11/16 Pensacola
1/7/18 O.K. see Q.P.
10/15/17

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List 7/5/18

A-123

TROUBLE REPORTS

Date

2

Station

Remarks

4-4198

June 18 Pensacola Fla. Pilot stalled machine in making turn at same time skidding. Pilot did not have enough altitude to recover before airplane crashed into the bay. Pilot was nervous & failed to handle airplane properly skidding on the turn stalled machine & crashed in to bay. Wrecked beyond repair few parts salvaged. Airplane struck from the list useful parts & fittings returned.

Des. No. A-124

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-9

S. E.

Bu-17

Cost Price
Flat Price

Contractor

Curtiss Aeroplane Co.

Address

Buffalo, N.Y.

Model

Type N-9 Hydro-Tractor School

Motor

H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

12/11/16 Pensacola
 9/21/18 Key West - In service.
 3/17/18 see Q.P.
 6/30/18 see Q.P. O.K.
 11/2/17 repaired. Paid at Key West Oct 31

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

521

17

Total Flying Time

Hours

Minutes

Stricken from Navy List

~~7/25/18~~ Reinstated 5-15-18
4198 11/23/18

TROUBLE REPORTS

4-4198

Date

Station

Remarks

2 A-124

4/15/19

Key West

Seaplane unfir for further service. Worn out with service. Recommended to be stricken from list .

Des. No. A-125

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-9

S. E.

Bu-17

Cost Price
Flat Price

Contractor **Curtiss Aeroplane Co.**

Address **Buffalo, N.Y.**

Model Type **N-9 Hydro-Tractor School**

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Accepted

Op. Air	Date	Wire	S. Order	Shipped	Destination	Received
	12/11/16				Pensacola	
	6/30/18				see O.K. unset.	
	1/27/18				Ill. see Q.P.	
	4/15/18				see Q.P. rebuilding	

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

7/15/18

TROUBLE REPORTS

4-4198

Date

Station

Remarks

2 A-125

Quincy's Naval Air Sta

Machine total wreck few parts & fittings saved
 Machine crashed in mid-air with no chance
 A-104 while making right turn near Life Saving
 Sta block Pilot killed instantly Remembered
 that Airplane be struck from Naval Air
 Craft list & all removable parts & fittings
 retained as spares in use at this Sta!
 Used for spares. Pilot killed.

Des. No. A- 126

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-19

S. E.

Bu-18

Cost Price
Flat Price

Contractor

Farman

Address

Model

Type

Motor

H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air

Date

Wire

S. Order

Shipped

Destination

Received

5/20/17 Pensacola
6/30/18 " - under overhaul
10/24/17 Transferred to Phila.

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

none

Hours

Pensacola

Minutes

Stricken from Navy List

12/23/18 - 0146-C-128 ⁴⁻⁴¹⁹⁸

TROUBLE REPORTS

4-4198

2

Date	Station	Remarks
11/29/18	Bensacola,	Farman Seaplane A-126 is not in good condition owing to service. It is recommended that this plane be stricken from the list.

Des. No. A- 127

AIRCRAFT RECORD

Des. No. A- ..

Contract No.

Req. CR-19

S. E.

Bu-18

Cost Price
Flat Price

Contractor **Farman**

Address

Model Type

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air	Date	Wire	S. Order	Shipped	Destination	Accepted	Received
<i>Contract canceled</i>							

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time Hours Minutes Stricken from Navy List

Des. No. A-128

AIRCRAFT RECORD

5169
5177

Des. No. A-

Contract No.

Req. ONA-3 1917 S. E.

Bu-

Cost Price
Flat Price

Contractor

Sturtevant Aero Co.

Address Jamaica Plains, Mass.

Model

Type Hydro-Tractor

Motor

H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air

Date

Wire

S. Order

Shipped

Destination

Jeff Accepted

Received

12/18/17 Mass. Inst. Tech.
1/9/19 Mass. Inst. Tech. R. Hour, Out

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

1/28/19

2

TROUBLE REPORTS

Date

Station

Remarks

1/4/19

M.I.T. Cam. Mass. Plane has been used for demonstrating rigging. It has been setup and torn down by the students for the past eleven months and its present condition is worthless. Recommended that Sturtevant be stricken from list.

Des. No. A- 129

AIRCRAFT RECORD

3764
5124

Des. No. A-

Contract No.

Req. **ONA-3 1917 S. E.**

Bu-

Cost Price
Flat Price

Contractor **Sturtevant Aero Co.**

Address **Jamaica Plains, Mass.**

Model Type **Hydro-Tractor**

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 94% 95% 100% F. O. B.

Op. Air	Date	Wire	S. Order	Shipped	Destination	Accepted	Received
					<i>July</i>	<i>Aug.</i>	<i>Sept.</i>
				<i>12/18/17</i>	<i>Mass. Inst. Tech.</i>	<i>Dec.</i>	

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time Hours Minutes Stricken from Navy List *1/25/19*

2

TROUBLE REPORTS

Date

Station

Remarks

4-4198

I/4/I9 M.I.T.Cam.Mass. Plane has been used for demonstrating Rigging. It has been set up and torn down by students for the past eleven months and its present condition is worthless. Recommended that Sturtevant be stricken from Navy list.

Des. No. A- 130

AIRCRAFT RECORD

5169
5149

Des. No. A-

Contract No.

Req. **CNA-3 1917 S. E.**

Bu-

Cost Price
Flat Price

Contractor **Sturtevant Aero Co.**

Address **Jamaica Plains, Mass.**

Model Type **Hydro-Tractor**

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air	Date	Wire	S. Order	Shipped	Destination	Accepted	Received
				<i>July</i>	<i>Sept</i>	<i>Oct Dec</i>	

12/15/17 Hampton Roads.
1/9/18 San Diego
Ground school

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time	Hours	Minutes	Stricken from Navy List
			<i>Stricken</i>

Des. No. A- 131

AIRCRAFT RECORD

5170
5750

Des. No. A-

Contract No.

Req. ONA-3 1917 S. E.

Bu-

Cost Price
Flat Price

Contractor

Sturtevant Aero Co.

Address

Jamaica Flains, Mass.

Model

Type Hydro-Tractor

Motor

H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air	Date	Wire	S. Order	Shipped	Destination	Accepted	Received
				July 1917	aug. Sept.	Oct. Nov. Dec.	

12/15/17 Hampton Roads
 9/25/18 San Diego
 1/3/18

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

10/24/18

2

TROUBLE REPORTS

Date

Station

Remarks

Aug 30/18 Miami Fla.

Crank shaft broken connecting rod broken sump broken, Crank case broken & 2 cylinders broken. Valve trunk balanced propeller & engine fed firing stuff. Oil. Recommended that motor no. 181 be stricken from list. parts used as spares.

Aug 22/18 Miami Fla.

Connecting rod, crankcase & sump broken. due to connecting rod breaking, caused by wrist pin freezing. Recommend motor # 8391 be stricken from list and parts remaining used as spares. For ground instruction.

2

TROUBLE REPORTS

Date

Station

Remarks

4-4198

Plane 132

Let G. L. T. Station

2-20-24

(705-2)

21799

Des. No. A-133

AIRCRAFT RECORD

5132
5153 Des. No. A-

Contract No.

Req. CNA-3 1917 S. E.

Bu-

Cost Price
Flat Price

Contractor

Sturtevant Aero Co.

Address

Jamaica Plains, Mass.

Model

Type Hydro-Tractor

Motor

H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air Date Wire S. Order Shipped Destination Accepted Received

July

aug. Sept.

Oct. Nov. Dec.

1/25/18 Great Lakes Naval Training Station

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

4-11-21

Des. No. A-134

AIRCRAFT RECORD

5159

Des. No. A-

Contract No.

Req. CR-20

S. E.

Bu-17

Cost Price
Flat Price

Contractor Thomas Morse Co.

Address Ithaca, N.Y.

Model Type Hydro-Tractor

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air	Date	Wire	S. Order	Shipped	Destination	Accepted	Received

8/13/17 Squantum, M.
 10/1/17 Hampton Roads.
 N. T. S.

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

*No record
not reported from any station*

Total Flying Time	Hours	Minutes	Stricken from Navy List	4-4185

2

TROUBLE REPORTS

Date

Station

{ Nov 16/17
see trouble
report }

Curtiss OX-3.

Remarks

4-4198

Used in Post office for
at N. T. D. for [unclear]

Des. No. A-135

AIRCRAFT RECORD

5758

Des. No. A-

Contract No.

Req. CR-20

S. E.

Bu-17

Cost Price
Flat Price

Contractor

Thomas Morse Co.

Address

Ithaca, N.Y.

Model

Type Hydro-Tractor

Motor

II. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Op. Air

Date

Wire

S. Order

Shipped

July Aug.
Destination

Accepted

Received

8/13/17 Squantum Ms
10/1/17 Hampton Roads
11/25/18 Gloucester

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

6/9/19

4-4198

2

TROUBLE REPORTS

4-4198

Date

Station

Remarks

1/29/19

N.A.F.

Curtiss OXX-3.

Trouble. Letter, CR.702-Z-0-18. (A) Oct.14, 1918.

*Minor repairs necessary throughout machine
Recommend to sell.*

Des. No. A-136

AIRCRAFT RECORD

5759

Des. No. A-

Contract No.

Req. CR-20

S. E.

Bu-17

Cost Price
Flat Price

Contractor Thomas-Morse Co.

Address Ithaca, N.Y.

Model Type Hydro-Tractor

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air	Date	Wire	S. Order	Shipped	Destination	Accepted	Received

8/24/17 Pensacola - without motor
 8/27/17 San Diego
 9/5/18
 10/15/18 Q.P. 6/20/18 Q.P. ground
 4/5/18 instruction use

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Carliss OXX-3

Total Flying Time

Hours

Minutes

Stricken from Navy List

10/24/18

4-4186

Des. No. A-137

AIRCRAFT RECORD

5160

Des. No. A-

Contract No.

Req. CR-21

S. E.

Bu-17

Cost Price
Flat Price

Contractor Standard Aircraft Corp.

Address Elizabeth, N.J.

Model Type Hydro-Tractor

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

June July Accepted

Op. Air	Date	Wire	S. Order	Shipped	Destination	Received
				7/7/17	Newport News	11/18 Gloucester
				12/21/17	Hampton Roads	
				11/25/18	Gloucester	
					Langley Field Va	

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

6/9/19

2

TROUBLE REPORTS

4-4198

Date

Station

Remarks

I/29/19

N.A.F.

Trouble. Letter, CR.702-Z-0-18.(A) 10/14/18.

*Motor missing, minor repairs necessary
throughout entire machine.*

Recommend to sell.

Des. No. A- 138

AIRCRAFT RECORD

3762
Des. No. A-
Cost Price
Flat Price

Contract No.

Req. CR-21

S. E.

Bu-17

Contractor

Standard Aircraft Corp.

Address

Elizabeth, N. J.

Model

Type Hydro-Tractor

Motor

IL P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Op. Air

Date

Wire

S. Order

Shipped

July to Nov. to
October Feb. 18
Destination

Accepted

Received

2/3/18 Hampton Roads

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

5/29/18

Jes. No. A-139

AIRCRAFT RECORD

5762

Des. No. A-

Contract No.

Req. CR-21

S. E.

Bu- 17

Cost Price
Flat Price

Contractor **Standard Aircraft Corp.**

Address **Elizabeth, N.J.**

Model **Type Hydro-Tractor**

Motor **H. P.**

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

*July to Dec, 17, to
Nov. to Feb-18.*

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

2/3/18 Hampton Roads

10/19/18 Gloucester

*(From card) Sold to W. R. Davis, Jr. Oakland, Cal on 11-7-18
10/30/19*

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

6/9/19

4-1108

2

TROUBLE REPORTS

4-1188

Date Station

Remarks

1/29/19

N.A.F.

Trouble. Letter, CR.702-Z-0-18. 10/14/18.

complete in original boxes as shipped from factory.
Provided these machines are not to be used for the purposes intended it is recommended that they be sold.

es. No. A-140

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-23

S. E.

Bu- 17

Cost Price
Flat Price

Contractor Thomas Morse Co.

Address Ithaca, N.Y.

Model Type Hydro Twin Tr.

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

Contract cancelled

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time Hours Minutes Stricken from Navy List 7/31/17

Des. No. A-141

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-23

S. E.

Bu-17

Cost Price
Flat Price

Contractor Thomas Morse Co.

Address Ithaca, N.Y.

Model Type Hydro Twin Tr.

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air	Date	Wire	S. Order	Shipped	Destination	Received

8/21/17 Bay Shore
8/24 Mass. Inst. Tech
Cont. cancelled.

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List 7/31/17

Des. No. A-142

AIRCRAFT RECORD

3184

Des. No. A-

Contract No.

Req. CR-26

S. E.

Bu- 17

Cost Price
Flat Price

Contractor

Aeromarine Eng. & Sales Co.

Address New York, N.Y.

Model

Type 2 Place Tractor

Motor

H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air Date Wire S. Order Shipped Destination Accepted Received

JULY
1918

				8/21/17	Bay Shore		
				5/24	Mass. Inst. Tech.		
				11/6/17	Bayshore.	(OVERHAULD)	T.R. 3/29/18 Bayshore
				1/9/19	T.R. Rec'd incomplete from	Bayshore	

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

1/28/19

TROUBLE REPORTS

4-4198

Date	Station	Remarks
3/23/18	Bay Shore	Seaplane lacks directional stability. Uncontrollable on water. Engine bed design faulty allowing excessive strain. Due to faulty design of stabilizing and control surfaces and pontoons. Plane and engine bed not strong enough to stand excessive vibration. Seaplane to be disassembled, parts to be kept for adaption as spares for aeromarine of new type of design.
1/4/19	M.I.T Cam. Mass.	Plane was received from Bay Shore out of condition and is worthless. Recommended that plane be stricken from Navy list.

Des. No. A-143

AIRCRAFT RECORD

5783 A.

Des. No. A-

Contract No.

Req. CR-26

S. E.

Bu-17

Cost Price
Flat Price

Contractor **Aeromarine Eng. & Sales Co.**

Address **New York, N.Y.**

Model Type **2 Place Tractor**

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

July AUG Accepted

Op. Air Date Wire S. Order Shipped

Destination

Received

8/10/17 Bay Shore

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

11/7/17

2

TROUBLE REPORTS

4-4188

Date	Station	Remarks
8/15/17	Bay Shore	Floats spread.
11/6/17	Bay Shore	Storm wrecked, being overhauled.
8/15/17	" "	Some of parts used to repair 440.

Des. No. A-144

AIRCRAFT RECORD

3785

Des. No. A-144

Contract No.

Req. CR-26

S. E.

Bu-17

Cost Price
Flat Price

Contractor **Aeromarine Eng. & Sales Co.**

Address **New York, N.Y.**

Model **Type 2 Place Tractor**

Motor **H. P.**

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95%⁹ 100% F. O. B.

Op. Air Date Wire S. Order Shipped

July AUG SEPT. Accepted
Destination

Received

*9/22/17 Pensacola
4/2/18 See Q.R.*

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

*Reported unfit for
further service
wrecked 1/12/18*

Total Flying Time

Hours

Minutes

Stricken from Navy List

2/26/18

4-4108

Des. No. A-145

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-43

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type H-14 Tr. Flying Boat

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Accepted

Op. Air	Date	Wire	S. Order	Shipped	Destination	Received
<i>Contract canceled</i>						

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List 1-16-17

4-4198

Des. No. A-146

AIRCRAFT RECORD

Des. No. A-146

Contract No.

Req. CR-43.

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type H-14 Tr. Flying Boat

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

*Contract cancelled
1/16/17*

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time Hours Minutes Stricken from Navy List

Des. No. A-147

AIRCRAFT RECORD

5200
5201

Des. No. A-

Contract No.

Req. CR-45

S. E.

Bu- 17

Cost Price
Flat Price

Contractor Pacific Aero Products Co.

Address Seattle, Wash.

Model Type Tractor

Motor H.P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

July Dec Accepted

Op. Air Date Wire S. Order Shipped Destination Received

7/27/17 Remacola
8/27/17 - San Diego
1/7/18 S. E. P.
4/13/18 rebuilding

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Grand Instruction

Total Flying Time Hours Minutes Stricken from Navy List

6/2/8

Des. No. A-

148

AIRCRAFT RECORD

3202
5203

Des. No. A-*

Contract No.

Req. CR-45

S. E.

Bu-17

Cost Price
Flat Price

Contractor Pacific Aero Products Co.

Address Seattle, Wash.

Model Type Tractor

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

July ~~1917~~ AUG Accepted

Op. Air Date Wire S. Order Shipped Destination Received

7/27/17 Pensacola
9/28/17 Pensacola wrecked
1/7/18 see Q.P.

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

No record - not reported by any station since - 1918
see trouble report 1/7/18

Total Flying Time Hours Minutes Stricken from Navy List 4-4108

5204

Des. No. A-149

AIRCRAFT RECORD

Des. No. A-

Contract No.	Req. CR-49	S. E.	Bu-17	Cost Price
				Flat Price
Contractor	Curtiss Engineering Corp.		Address	Garden City, L.I.
Model	Type	Triplane Tractor Speed Scout		
Motor	H. P.	Inspector		

PRODUCTION RECORD

10%	20%	30%	40%	50%	60%	65%	70%	75%	80%	85%	90%	95%	100%	F. O. B.
														Accepted
Op. Air	Date	Wire	S. Order	Shipped		Destination			Received					

SEPT. JULY OCT

AVG. 88%

11-26-17 Miami.
 1/12/18 Miami (see T. R.) *total motor saved.*

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time 3 Hours 40 Minutes Stricken from Navy List 1/31/18

TROUBLE REPORTS

4-4193

Date

Station

Remarks

2/21/18 Miami, Fla.

A-149 a total wreck, with the exception of motor. Pilot was making a fast landing and had traveled a distance of approximately fifty feet on the step when pontoon collapsed, causing machine to turn over. Recommended that this plane be stricken from the Naval list.

Des. No. A- 150

AIRCRAFT RECORD

3205

Des. No. A-

Contract No.

Reg. CR-49

S. E.

Bu-17

Cost Price
Flat Price

Contractor ~~Curtiss Engineering Corp.~~

Address Garden City, L.I.

Model Type Triplane Tractor Speed Scout

Motor H. P. Inspector

PRODUCTION RECORD

10%	20%	30%	40%	50%	60%	65%	70%	75%	80%	85%	90%	95%	100%	F. O. B.
		July		Sept							DEC. JAN. FEB.		OCT. NOV. MAR.	Accepted
Op. Air	Date	Wire	S. Order	Shipped							Destination			Received

0446-779 6-28-19

4/17/18

Miami

4/28/18

N. A. storehouse, Gloucester, N. J.

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

8-6-19

0196-016A

Des. No. A-151

AIRCRAFT RECORD

Des. No. A-

Contract No.	Req. CR-48	S. E.	Bu- 17	Cost Price Flat Price
Contractor	Goodyear Tire and Rubber Co.		Address	Akron, Ohio.
Model	Type	25,000 Kite Balloon		
Motor	H. P.	Inspector		

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air	Date	Wire	S. Order	Shipped	Destination	Received
---------	------	------	----------	---------	-------------	----------

<p>12/28/16 Pensacola</p> <p>10/15/17 " - Reported at.</p> <p>2-3-17 USS. NEVADA</p> <p>7-11-17??? USS. SEATTLE</p> <p>6-4-17 SUPPLY STS. N.Y.</p> <p>1/7/17 Lu Q.N.</p>	<p>{ Akron 10/24/18</p>
--	-------------------------

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time	Hours	Minutes	Stricken from Navy List	<u>Stricken 10/24/18</u> 8/24 - RECOMMENDED ⁴¹⁹⁸
-------------------	-------	---------	-------------------------	--

2

TROUBLE REPORTS

Date

Station

Remarks

4-4193

8/24/18. Pensacola. High diffusion due to deterioration caused by length of service. Balloon of this type now obsolete and opinion of board that on account of the bad state of fabric it is unsafe for use, and that balloons are of no use other than for the purpose of instructing D. M. S. in balloon fabric. Recommended that they may be so disposed of.

Des. No. A-152

AIRCRAFT RECORD

3211-5212
3213-8214

Engin No.

Des. No. A-

Contract No.

Req. CR-50

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type H-12 Flying Boat

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

3/23/17 Pensacola

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

1/7/18 See Q report

Total Flying Time

Hours

Minutes

Stricken from Navy List

2/9/18

Des. No. A-153

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req.

S. E.

Bu-

Cost Price
Flat Price

Contractor **Pensacola Exper. Navy Aero. Sta., Pensacola** Address

Model Type **Tractor**

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

July

AUG

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

8/9/17 Pensacola
11/9/17 Pensacola, being overhauled.

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List *12/22/17*

es. No. A- 134

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req.

S. E.

Bu-

Cost Price
Flat Price

Contractor

Address

Model

Type

Motor

H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Accepted

Op. Air

Date

Wire

S. Order

Shipped

Destination

Received

Completed

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

Des. No. A- 155

AIRCRAFT RECORD

Engine No. 5196
5197

Des. No. A-

Contract No. Req. CR-59 S. E. Bu-17 Cost Price Flat Price

Contractor Burgess Co. Address Marblehead, Mass.

Model Type H-T Types Speed Scout Tractor

Motor H. P. Inspector

PRODUCTION RECORD

10%	20%	30%	40%	50%	60%	65%	70%	75%	80%	85%	90%	95%	100%	F. O. B.
												JULY	AUG & SEPT.	Accepted
Op. Air	Date	Wire	S. Order	Shipped							Destination			Received

9/11/17 Squantum

Accessories Lacking at Shipment Bureau Advised Accessories Supplied

Total Flying Time Hours Minutes Stricken from Navy List 11/15/17

TROUBLE REPORTS

4-4193

2
Date

Station

Remarks

Oct 4. 1917 Squantum. Wrecked, considered beyond repair.

Des. No. A- 156

AIRCRAFT RECORD

5799
5198 *ground instruction*

Des. No. A-

Contract No.

Req. CR-59

S. E.

Bu-17

Cost Price
Flat Price

Contractor

Burgess Co.

Address

Marblehead, Mass.

Model

Type

H-T Types Speed Scout Tractor

Motor

H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

July

AUG

SEPT OCT

Accepted

Op. Air

Date

Wire

S. Order

Shipped

Destination

Received

1/2 1/8 1/2/18 S.O. Mass. Inst. Tech.

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

1/28/19

TROUBLE REPORTS

4-4198

2
Date

Station

Remarks

I/4/19 M.I.T.Cam.Mass. Plane was sent from Burgess and had not been completely built when received . Plane is worthless. Recommended that plane be stricken from Navy list.

Des. No. A- 157

AIRCRAFT RECORD

Engine No. 5246³²⁴⁸

Des. No. A-

Contract No.

Req. NSA-306 S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type JN-4 - 2 Pl.Tr

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

5/10/17 Marine A.B.V. Phila.
3/11/18-20 Miami

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time Hours Minutes Stricken from Navy List 5/20/18

TROUBLE REPORTS

4-4135

2

Date	Station	Remarks
5/11/18	Miami, Fla.	Total wreck. Aeroplane A-157 is to be considered a total wreck, and that it be dropped from the Navy list.

7/23/17 Chile
1-18-18

Wrecked.
Shop N.A.F.

Des. No. A- 158

AIRCRAFT RECORD ⁵²⁴⁷
₅₂₄₈

Des. No. A-

Contract No. Req. NSA-306 S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type JN-4 - 2 Pl.Tr.

Motor II. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Op. Air Date Wire S. Order Shipped

Destination

Received

5/10/17 Marine A.B.C. Phila.

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

No record - Not reported by any station

Total Flying Time

Hours

Minutes

Stricken from Navy List

2

TROUBLE REPORTS

Date Station

Remarks

9/30/17 Miami

Complete wreck, nothing saved.

Des. No. A- 159

AIRCRAFT RECORD

5249
5250

Des. No. A-

Contract No.

Req. NSA-306

S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type JN-4 - 2 Pl.Tr.

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air	Date	Wire	S. Order	Shipped	Destination	Received
---------	------	------	----------	---------	-------------	----------

5/10/17 Marine #132. Phila.
 5/11/18 A.C. Miami
 11/14/17 AT. Mid. So. Cal. I.
 12/27/17 A.B.U. Phila.

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

11/26/18

TROUBLE REPORTS

4-4198

2
Date

Station

Remarks

10/31/18 Marine Flying
Field, Miami,
Fla.

Longerons, compression members in fuselage and engine bed are warped. Wires crystalized, and a number of fittings worn out. Machine to be stricken from the Naval list of aircraft

Des. No. A-160

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-60

S. E.

Bu-17

Cost Price
Flat Price

Contractor **Goodyear Tire and Rubber Co.**

Address **Akron, Ohio.**

Model Type **25,000 Kite Balloon**

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

5/10/17 *Maryine B. V. Phila.*
12/11/17 *Rockaway*
M. Carolina
Brookings

Accessories Lacking at Shipment

Bureau Advised

495 *201-7-13*
Sept 29
Accessories Supplied

Total Flying Time Hours Minutes Stricken from Navy List *7/17/20*

Des. No. A-161

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. CR-60 S. E.

Bu-17

Cost Price
Flat Price

Contractor Goodyear Tire and Rubber Co.

Address Akron, Ohio.

Model Type 25,000 Kite Balloon

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

5/10/17 Marine U.S.V. Phila.

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

No record, not reported by any station.

Total Flying Time

Hours

Minutes

Stricken from Navy List

Des. No. A- 162

AIRCRAFT RECORD

5251
5252

Des. No. A-

Contract No.

Req. NSA-309

S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

6/20/17 Pensacola
8/27/17 Bay Shore
7/16/17 U.S.S. HUNTINGTON

Accessories Lacking at Shipment

Bureau Advised

~~Accessories Supplied~~

Aug 1917 damaged
By Gunfire

Total Flying Time

Hours

Minutes

Stricken from Navy List

11/7/18

Des. No. A- 163

AIRCRAFT RECORD

5253
5-2 57

Des. No. A-

Contract No.

Req. NSA-309

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.M.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

6/20/17 Pensacola
8/27/17 Bay Shore
7-16-17 U.S. HUNTINGTON.

Accessories Lacking at Shipment

Bureau Advised

~~Accessories Supplied~~

Aug 1917
Damaged by
Gunfire

Total Flying Time

Hours

Minutes

Stricken from Navy List 11/7/18

←4198

Des. No. A- 164

AIRCRAFT RECORD

5-255-
5-256

Des. No. A-

Contract No.

Req. NSA-309

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air	Date	Wire	S. Order	Shipped	Destination	Received
	6/26/17				Pensacola	
	11/5/17				Rockaway (comfort for service)	
	7/16/17				USS. Huntington	

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

* Minutes

Stricken from Navy List

11/14/17

Des. No. A-165

AIRCRAFT RECORD

5257
5-258

Des. No. A-1

Contract No.

Req. NSA-309

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

6/26/17 Pensacola
11/17/17 Rockaway (under overhaul)
7/16/17 USS Huntington.

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

8/5/18

TROUBLE REPORTS

4-4193

2
Date

Station

Remarks

7/22/18 Rockaway, L.I.N.Y. Entire seaplane has deteriorated due to old age and wear.

Reccomended that machine be stricken from Navy lists, motor and instruments to be kept for spare parts.

Des. No. A- **166**

AIRCRAFT RECORD

5259
5260

Des. No. A- **166**

Contract No.

Req. NSA-309 S. E.

Bu-17

Cost Price
Flat Price

Contractor **Curtiss Aeroplane Co.**

Address **Buffalo, N.Y.**

Model Type **R-6**

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Accepted

Op. Air	Date	Wire	S. Order	Shipped	Destination	Received
---------	------	------	----------	---------	-------------	----------

7/1/17 Sold to Army

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

4-1189

Des. No. A-167

AIRCRAFT RECORD

5261
5262

Des. No. A-167

Contract No.

Req. NSA-309 S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

7/1/17 Sold to Army

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time Hours Minutes Stricken from Navy List

Des. No. A-168

AIRCRAFT RECORD

5263
5264

Des. No. A-168

Contract No.

Req. NSA-309

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor ~~V-2 Curtiss~~ Liberty H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

6/22/17 U.S.S. N. Carolina

9/24/18 Gloucester, N.J.

11-2-17 Cape May.

50286
73119 8/5/19 N. A. F.

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

3266 3-12-20 Pensacola

8/19/19
3-29-20

Stricken List See Navy Aer M. 22. mL A4-1

Total Flying Time 296

Hours

38 Minutes

Stricken from Navy List

7-24-26

2

TROUBLE REPORTS

Date

Station

Remarks

4-4199

11/17/19 Cape May,

Seaplane 168- both lower wings and intermediate sections damaged beyond repair. All pontoon struts bent or broken, propeller broken one pontoon badly cut by propeller. Due to bad landing. Recommended that damaged pontoon be sent to the Navy Aircraft Factory, Philadelphia, for repairs.

1/18/18
6/16/22 Pensacola

Stop N. U. F.
Right pontoon damaged - forward fitting right pontoon broken - all wings water soaked - forward cockpit scorched by fire - Engine not damaged but does not warrant installation until overhaul due to being out - Heavier fittings to be installed - cut out cock grandly line - Plane & engine to be overhauled.

6-22-26 Pensacola A. 168 Old & deteriorated, (lt) det -
Strike from list

205555

Des. No. A- 169

AIRCRAFT RECORD ⁵²⁶⁰₅₂₆₆

Des. No. A-~~16~~

Contract No.

Req. NSA-309 S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

6/22/17 Newport News
9/17 Hampton Roads

Accessories Lacking at Shipment

Bureau Advised

~~Accessories Supplied~~

*6/18/18 Hampton -
Anft for
Service*

Total Flying Time

Hours

Minutes

Stricken from Navy List

11/26/18

Des. No. A- 170

AIRCRAFT RECORD

5267
5268

Des. No. A-

Contract No.

Req. NSA-309 S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

6/22/17
9/1/17
Newport News
Hampton Roads

Accessories Lacking at Shipment

Bureau Advised

~~Accessories Supplied~~

3/12/18 Hampton
wrecked

Total Flying Time Hours Minutes Stricken from Navy List 5/18/18

Des. No. A- 171

AIRCRAFT RECORD

5269
5270

Des. No. A-1

Contract No.

Req. NSA-309 S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Accepted

Op. Air	Date	Wire	S. Order	Shipped	Destination	Received
	7/21/17				Newport News	
	9/1/17				Hampton Roads	
					" "	

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List 11/15/17

TROUBLE REPORTS

4-4198

2
Date

Station

Remarks

Hampton Ad. Wrecked. Recommended by per Rec. Letter
Oct. 29/17.

Des. No. A-172

AIRCRAFT RECORD

5-271

5-272

Des. No. A-1

Contract No.

Req. NSA-309

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor Liberty H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

5-10-19 7/21/17 Pensacola
2159 7-5-19 Gloucester Op Air 0146-887

1-8-20 Philadelphia, N.A. F.
3300 5-10-20 San Diego (Pacific Fleet) 7-1-20

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Stricken list per M-24-acc
1-12 1/24/22

Total Flying Time

Hours

Minutes

Stricken from Navy List

1/24/22

TROUBLE REPORTS

4-4198

Date

Station

Remarks

2

1/7/18
6/30/18
9/29/22

San Diego

See Q.R.

Q.R. under over haul.

A. 172 all fuselage fittings fitted and rusted beyond repair. Incident to long service expend & consign to scrap heap - See my - 22-23 9/29/22 B.S.

Des. No. A-173

AIRCRAFT RECORD ⁵²⁷³ ₅₂₇₄

Des. No. A-

Contract No.

Req. NSA-309 S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped

Destination

Received

7/24/17 Pensacola
6/30/18 O. R. O. N.

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time 184

Hours 35 Minutes

Stricken from Navy List

12/23/18

-0144-C-275-4198

2
TROUBLE REPORTS

Date

Station

Remarks

4-4195

6/20/18 Pensacola.

This pontoon was borrowed from Seaplane A-177, in order to maintain 173 in service. On return to the Beach the outer keel was found partially carried away. Recommended that repairs be made locally.

11/39/18 Pensacola

R-3 Seaplane #A-173 is not in good condition owing to service. It is recommended that this plane be stricken from list.

Des. No. A-174

AIRCRAFT RECORD

3275
3276

Des. No. A-

Contract No.

Req. NSA-309 S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air	Date	Wire	S. Order	Shipped	Destination	Received
				7/23/17	Huntington, L.I.	
				12/20/17	Miami	
				9/1/17	Bay Shore, Gloucester	

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

3-7-19

Des. No. A-175

AIRCRAFT RECORD

5277 Engine O. K.
5278

Des. No. A-

Contract No.

Req. NSA-309

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model

Type R-6

Motor

H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air	Date	Wire	S. Order	Shipped	Destination	Received
				7/27/17	Huntington, L.I. N.Y.	
				9/1/17	Bay Shore, L.I.	

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

11/10/17 Reported
Unfit

Total Flying Time

Hours

Minutes

Stricken from Navy List 11/23/17

Des. No. A- 176

AIRCRAFT RECORD

5279
5280

Des. No. A-

Contract No.

Req. NSA-309

S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

7/30/17 Pensacola
Gloucester Op Air 0146-887

Stricken No record Rep. R. A. F. 7/31/22

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time Hours Minutes Stricken from Navy List

2

TROUBLE REPORTS

Date

Station

Remarks

4-4198

8/21/18 Pensacola,

On examination in the Hanger, this fitting was found broken. The break appears to be due to the combined effect of burning when brasing, and to insufficient material to stand the loads imposed. Repairs recommended locally.

*See Q Report
Reported condemned.*

*1/7/18
1/15/18*

Des. No. A-177

AIRCRAFT RECORD 528I 5282

Des. No. A-177

Contract No.

Req. NSA-309

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model

Type R-6

Motor

Liberty

H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Accepted

Op. Air

Date

Wire

S. Order

Shipped

Destination

Received

5-10-19 8/1/17 Pensacola
2159 7-5-19 Gloucester Op Air O146-887
N. A. F.
1476 1-15-21 Pensacola.

yes.
2-5-21

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

See Navy
Stricken Let. Aer. M-22 EHP. 7-12 11-14-24

Total Flying Time 11-24

Printed Op Air O146-S-483 Dated 4-11-19

Hours

Minutes

Stricken from Navy List

3-7-19 11-14-24

4-119

TROUBLE REPORTS

4-4193

Date

Station

Remarks

- | | | |
|----------|-----------|--|
| 8/20/17 | Pensacola | Float damaged. |
| 1/7/18 | | See Q. Report. 6/30 Q. R. O.K. |
| 11/23/22 | Pensacola | Q. 177 Upper & lower right & lower left wings damaged at .
The board recommends the H-4 strut installation be installed in R. 62's & further that a more careful inspection by erecting shops & pilots be made after erection, overhauling, & any change. Repair floats etc. - The engine to be installed when the plane is re-assembled. |
| 9-26-24 | Pensacola | Q. 177 Both lower wings, both wing sections, upper wing section & right locker longeron. Eng 709 - undamaged. Aircraft to be stricken - Eng to be 6 to |

Des. No. A-178

AIRCRAFT RECORD

5283
5284

Des. No. A-1

Contract No.

Req. NSA-309 S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model *Liberty* Type R-6

Motor *Curtiss 473* H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air Date Wire S. Order Shipped

July Aug. Accepted

Destination

Received

8/11/17 Squantum
10/1/17 Hampton Roads
10/27/18 N. A. S. Gloucester
8/5/19 G. G. F.

*S. O. 2646
7-31-18*

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

8/19/19

*No record - G. G. F. lib. 6/30/22 704-0
404-1*

Total Flying Time

Hours

Minutes

Stricken from Navy List

Des. No. A-179

AIRCRAFT RECORD

5285
5286

Des. No. A-1

Contract No.

Req. NSA-309

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

July AUG. Accepted

Op. Air Date Wire S. Order Shipped Destination Received

8/9/17
10/1/17
Squantum
Hampton, Rds.

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

6/14/18

Des. No. A-189

AIRCRAFT RECORD

5-287
5285

Des. No. A-

Contract No.

Req. NSA-309

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Op. Air Date Wire S. Order Shipped

July

AUG

Accepted

Destination

Received

8/14/17 Pensacola

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List 2/26/18

1/27/18 See Q report
4-119

Des. No. A- 181

AIRCRAFT RECORD

5249
5290

Des. No. A-

Contract No.

Req. NSA-309

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80%² 85% 90% 95% 100%

F. O. B.

July

~~Aug~~ Aug

Accepted

Op. Air

Date

Wire

S. Order

Shipped

Destination

Received

8/14/17 Pensacola

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

7/5/18

2

TROUBLE REPORTS

Date Station

Remarks

June 9/18 Pensacola Fla. Seaplane completely destroyed by fire at 7:15 p.m.
 May 14/18 Seaplane in beach resting time
 of fire, gas tanks were being filled for next
 flight. Flames burst from left side of
 engine tank. Few seconds plane was completely
 destroyed except (1) uninterchangeable piston
 which could not be found. Chimney of
 motor caused ignition of gasoline from
 gas. & still burning from @ previous flight.
 1/7/18 See O. Report. It is recommended that the seaplane be
 stricken from the list & the serviceable
 parts & fittings be retained at Sparrow
 Hill station.

Des. No. A-182

AIRCRAFT RECORD

5291
5292

Des. No. A-

Contract No.

Req. NSA-309

S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

July

AVG

Accepted

Op. Air Date Wire S. Order

Shipped

Destination

Received

8/17/17 Pensacola

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

1/7/18 See Q report

Total Flying Time

Hours

Minutes

Stricken from Navy List

5/27/18

Des. No. A- 183

AIRCRAFT RECORD

5-293
5-294

Des. No. A-

Contract No.

Req. NSA-309

S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N. Y.

Model Type R-6

Motor *Liberty*
Curtiss V-3 H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

July

AUG

Accepted

Op. Air	Date	Wire	S. Order	Shipped	Destination	Received
---------	------	------	----------	---------	-------------	----------

8/14/17 Pensacola

San Diego

11/20/18 Gloucester

*7-31-19
2646*

8-15-19 NAF

Accessories Lacking at Shipment.

3266

*1-27-20 Bureau Advised
Pensacola*

2-15-19

8/19/19

Accessories Supplied

2-17-20

Total Flying Time

Hours

Minutes

Stricken from Navy List

9-14-20

←4108

TROUBLE REPORTS

4-4193

2
Date

Station

Remarks

12/22/17
1/5/18

8/10/20

Pensacola

*Wrecked.
See Q Report
Q.R. 6/30 under overhaul*

A-183 crashed to complete wreck in Pensacola Bay. Recommended that plane be stricken from the Navy list.

Des. No. A- 184

AIRCRAFT RECORD

5295 Spone
5296

Des. No. A-

Contract No.

Req. NSA-309 S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air Date Wire S. Order Shipped Destination Received

July

AVG

Accepted

8/18/17 Huntington L.I.
12/20/17 Miami
8/1/17 Bay Shore

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time Hours Minutes Stricken from Navy List 3/4/18

TROUBLE REPORTS

2
Date

Station

Remarks

4-4198

2/25/18 Miami, Fla.

Seaplane A-184 a total wreck with exception of engine. The pilot was flying at an altitude of about 500 feet, when oil lead to cam shaft broek throwing oil on face of pilot who was unable to make a successful landing on account of being blinded by oil. Recommended that seaplane be stricken from the Navy list.

Des. No. A-185

AIRCRAFT RECORD

5297
5298

Des. No. A-

Contract No.

Req. NSA-309

S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model

Type R-6

Motor

H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

July

AVG

Accepted

Op. Air

Date

Wire

S. Order

Shipped

Destination

Received

8/23/17
12/20/17
7/1/17

Huntington, L.I.
Miami
Bay Shore.

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

7/15/18

2 TROUBLE REPORTS

Date

Station

Remarks

4-4193

7/1/18 Miami Fla. Seaplane A-185 a total wreck with exception of motor
plant, outer wing section, Fabric on outer wing
section badly deteriorated. Recommended to be
stricken from the Naval List, retaining motor and
outer wing sections as spares.

Des. No. A-186

AIRCRAFT RECORD

3-299
53-1-1

Des. No. A-

Contract No.

ReqNSA-309

S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air	Date	Wire	S. Order	Shipped	Destination	Accepted	Received
			July			AUG	

8/24/17 Bay Shore
Ontauk

Accessories Lacking at Shipment

Bureau Advised

~~Accessories Supplied~~

Prof Phila - Expended

Total Flying Time

Hours

Minutes

Stricken from Navy List 10-24-18,

Des. No. A- 187

AIRCRAFT RECORD

5301
5302

Des. No. A-

Contract No. Req. NSA-309 S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

July

AUG

Accepted

Op. Air Date Wire S. Order Shipped

Destination

Received

01467-76 628/18

8/24/17 Bay Shore
Montauk

p. am 0146-76 dated
6/25/18

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time Hours Minutes Stricken from Navy List 8/5/18

TROUBLE REPORTS

4-4193

Date

Station

Remarks

2
 July 23, 18 McLean Station All cover fittings, clamps, follow through the lines, loose & turned back, badly rusted, some "key" through metal clevis pins & clevises so, some with rust. Buckle & screws, oxidized & rotted (1/4 of an inch) and water on the ground tanks leak. Minimum of 13 Brand is no longer fit for patrol service. (Recommended) Purchase & supply to McClelland Aircraft Factory, Phila. for support. Wing & pantons practice again - fit for Lutten use. Replenish 177 strikes from Army tank.

2 Des. No. A- 188

AIRCRAFT RECORD

5303
5304

Des. No. A-

Contract No.

Reg. NSA-309

S. E.

Bu-17

Cost Price
Flat Price

Contractor

Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model

Type R-6

Motor

H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40%^F 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F.O.B.

JULY

AUG

Accepted

Op. Air

Date

Wire

S. Order

Shipped

Destination

Received

0146-I-76 6/28/18

8/24/17 Bay Shore
Montauk
11/12/18 N.G. F. Phila.

op. air 0146-I-76 dated 6/24/18

Accessories Lacking at Shipment.

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

1/23/19

2

TROUBLE REPORTS

Date

Station

Remarks

12/30/18	N.A. F. Chula	Unfit for service. Recommended expended.
1/23/19	N.A. N.	Expended - Unfit

Des. No. A-189

AIRCRAFT RECORD ⁵³⁰⁵₅₃₀₆

Des. No. A-

Contract No.

Req. NSA-309

S. E.

Bu-17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

July

Aug. Dept.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

8/27/17 Phila. Navy Yard
11/12/17 Cape May

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

11/21/17

Des. No. A- 190

AIRCRAFT RECORD

5-307
5305

Des. No. A

Contract No.

Req. NSA-309

S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air Date Wire S. Order Shipped Destination Accepted Received

Ju. 9

Aug

SEPT

9/12/17 M. G. B. G. Phila.
11/1/17 Cape May

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List *2/22/18*

TROUBLE REPORTS

4-4195

2

Date Station

Remarks

3/19/18 Cape May,

The fuselage was severed at the rear cock-pit and the longerons broken and cracked, the control wheels were split from swelling although the yokes are still intact. All control wires were broken, also brace wires. The rear cowl was broken but the forward cowl was practically intact including the gas tanks. The longeronside plates, and the engine hood were intact and the radiator slightly dented at the top. The seaplane is wrecked beyond possibility of repair, and it is recommended to be stricken from the list.

2/8/17 Cape May Unfit for service

Des. No. A- 191

AIRCRAFT RECORD ⁵⁻³⁰⁹
₅₅₁₀

8
Des. No. A-

Contract No.	Req. NSA-309	S. E.	Bu- 17	Cost Price Flat Price
Contractor	Curtiss Aeroplane Co.		Address	Buffalo, N.Y.
Model	Type	R-6		
Motor	H. P.		Inspector	

PRODUCTION RECORD

10%	20%	30%	40%	50%	60%	65%	70%	75%	80%	85%	90%	95%	100%	F. O. B.
		<i>July</i>									<i>Aug</i>	<i>SEPT</i>	Accepted	Received
Op. Air	Date	Wire	S. Order	Shipped							Destination			

8/31/17 *Quantum*
10/17/ *Hampton Roads*
Quantico Va?

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time	Hours	Minutes	Stricken from Navy List	<i>3/31/19</i>
-------------------	-------	---------	-------------------------	----------------

Des. No. A-192

AIRCRAFT RECORD

5811
5812

Des. No. A-...

Contract No.

Req. **NSA-309** S. E.

Bu-17

Cost Price
Flat Price

Contractor **Curtiss Aeroplane Co.**

Address **Buffalo, N.Y.**

Model Type **R-6**

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air	Date	Wire	S. Order	Shipped	Destination	Accepted	Received
	<i>July</i>				<i>Aug.</i>	<i>Sept.</i>	

8/30/17
10/17/ *Squantum*
Hampton Roads

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List *7/5/18*

Des. No. A-193

AIRCRAFT RECORD

5313
5314

Des. No. A-

Contract No.

Req. NSA-309 S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor Liberty H. P.

Inspector

PRODUCTION RECORD

10% 20%⁵ 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F.O.B.

July

Aug

Sept, Accepted

Op. Air Date Wire S. Order Shipped Destination Received

5-10-19 2159 9/5/17 Pensacola
7-5-19 Gloucester Op Air O146-887
N.A. F.
1476 1-15-21 Pensacola

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Yes
1-31-21

Total Flying Time

Hours

Minutes

Stricken from Navy List

2/11/22

4-4198

2

TROUBLE REPORTS

Date

Station

Remarks

4-410s

11/7/18

*See Q. Report
OP. 6/30 O. H.*

11/23/21 Pensacola.

*Crashed to a total wreck.
(Pens. tel. 1523-1620)*

11-23-21 Pensacola

Plane a complete wreck, all structural parts damaged beyond repairs except rudder, vertical stabilizer, one non-skid, one upper and one lower aileron which minor repairs can put in a serviceable condition. Engine not damaged, but requires overhauling due to being wet.

Des. No. A-194

AIRCRAFT RECORD

5-210
5-316

Des. No. A-

Contract No.

Req. NSA-309

S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model

Type R-6

Motor

H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

July

AUG

SEPT.

Accepted

Op. Air

Date

Wire

S. Order

Shipped

Destination

Received

9/11/17 Pensacola

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

5/27/18

2

TRouble REPORTS

Date

Station

Remarks

4-4198

3/13/18 Pensacola,

Rudder jammed while pilot was trying to recover from spinning nose dive. Pilot failed to release rudder and was unable to stop spinning before seaplane nosed into water. Seaplane completely wrecked. Recommended that this seaplane be stricken from the list.

Des. No. A-195

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req. NSA-309 S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10%	20%	30%	40%	50%	60%	65%	70%	75%	80%	85%	90%	95%	100%	F. O. B.
<i>July</i>										<i>AUG</i>			<i>SEPT</i>	Accepted <i>Ball checked</i>
Op. Air	Date	Wire	S. Order	Shipped		Destination			Received					

9/4/17 N. Carolina
11/5/17 Cape May

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time *30* Hours *43* Minutes Stricken from Navy List *10/24/18*

TROUBLE REPORTS

4-4193

Date

Station

Remarks

10/2/18 Cape May

Unfit for further use. Recommended that this plane be stricken from the Naval List of Aircraft.

10/24/18 Cape May

Expended

Des. No. A-196

AIRCRAFT RECORD

5319
5820

Des. No. A-

Contract No.

Req. NSA-309 S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type R-6

Motor H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

dv/s

AVG

SEPT

Accepted *Checked*

Op. Air Date Wire S. Order Shipped Destination Received

9/20/17 N. Carolina
11/5/17 Cape May

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time Hours 5 Minutes Stricken from Navy List 8/15/18

TROUBLE REPORTS

4-4198

Date

Station

Remarks

2
7/27/18 Wake Key,

Seaplane A-196 was totally wrecked. Due to a tail-spin from 800 ft. The pilot claims that an air gust struck the plane under the tail throwing the machine into a tail spin. Recommended that this plane be stricken from the Naval List. **Pilot bruised.**

Des. No. A- 197

AIRCRAFT RECORD

5321
5322

Des. No. A-

Contract No. Req. NSA-309 S. E. Bu- 17 Cost Price
 Contractor Curtiss Aeroplane Co. Address Buffalo, N.Y. Flat Price

Model Type R-6

Motor H. P. Inspector

PRODUCTION RECORD

5% 10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

Outfitted
F. O. B.

du/y *AUG* *SEPT Oct.* Accepted Received

Op. Air Date Wire S. Order Shipped Destination Accepted Received

9/24/17 N. Carolina
11/5/17 Cape May

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time Hours Minutes Stricken from Navy List *4/13/18*

2 TROUBLE REPORTS

Date

Station

Remarks

4-4198

3/23/18 Cape May,

Practically everything was destroyed, including the fuselage, wing sections, one pontoon, struts, wires, propeller, three ailerons, and one flipper. Recommended that this plane be stricken from the list of Navy Aircraft.

Des. No. A- 198

AIRCRAFT RECORD ⁵³²³ ₅₃₂₀

Des. No. A-

Contract No.

Req. CR-65 S. E.

Bu- 17

Cost Price
Flat Price

Contractor Curtiss Aeroplane Co.

Address Buffalo, N.Y.

Model Type JN-Twin Engine Tractor

Motor H. P. Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

July *Aug* *SEPT* *Oct, Nov,*
Op. Air Date Wire S. Order Shipped Destination

Accepted

Received

11/27/17 Wash. D.C.
10/18 Gloucester.
transfer
5-6-19 Philadelphia

5-7-19

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

7-10-19

←4198

es. No. A - 1994-200

AIRCRAFT RECORD

Des. No. A- ,

Contract No.

Req.

S. E.

Bu-

Cost Price
Flat Price

Contractor

Address

Model

Type

Motor

H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Accepted

Op. Air

Date

Wire

S. Order

Shipped

Destination

Received

Cancelled

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

TROUBLE REPORTS

Date

Station

Remarks

4-4195

